NetShelter Rack PDU Advanced
Sensor Hub APDU1300
Installation



IMPORTANT INFORMATION

The Sensor Hub allows you to use multiple Temperature and Humidity sensors all monitored by a single NetShelter® Rack PDU Advanced.

NOTICE
The APDU1300 Sensor Hub can be used to connect the APDU1335T Temperature Sensor Assembly (not provided) or the APDU1335TH Temperature/Humidity Sensor Assembly (not provided) to your NetShelter Rack PDU Advanced. Connecting the APDU1335T3H Temperature/Humidity Sensor Assembly (not provided) to an APDU1300 Sensor Hub is not recommended.

Inventory



❶	Sensor Hub (Qty 1)
❷	Double-sided Adhesive Mounting Tape (Qty 1)
❸	Cable Ties (Qty 5)

Installation



Peel the protective cover material from one side of the Double-sided Adhesive Mounting Tape ❶. Press the exposed adhesive on the Mounting Tape to your chosen installation location inside the rack. Peel the protective cover material from the other side of the Mounting Tape ❷ and press the Sensor Hub to the exposed adhesive on the Mounting Tape ❸.

Example: Sensor connections to the Sensor Hub and the NetShelter Rack PDU Advanced



Connect up to three (3) sensor cables with RJ45 connectors (not provided) to the Sensor Hub ❶. Connect another RS–485 Cable (not provided), with RJ45 connectors ❸ at each end, from the Sensor Hub ❶ to Port 1 ❹ or Port 2 ❷ of the NetShelter Rack PDU Advanced.

NOTE: It may take a few minutes for the NetShelter Rack PDU Advanced to acknowledge the connection to the sensors.

Worldwide Customer Support

Customer support and warranty information is available at **www.apc.com**

© 2022 Schneider Electric. All rights reserved.

990-91602 4/2022